



Italia

CONCLUSIONS

Taking into account the specific testing outfit and the testing modalities used and above described, the recorded stem seal leak values satisfy the requirement as per TA-Luft Regulation of 18 August 2021 (Ref. G.M. No. G3191A of 14 September 2021 – Par. 5.2.6.4)

**Valve reported in this certificate can be qualified according to TA-Luft Regulation of 18/09/2021 (Ref. G.M. No. G3191A of 14/09/2021 – Par. 5.2.6.4)
Qualification may be extended to untested valves as per ISO 15848-1 - Par. 8.0.**

This certificate is valid only if referred to Inspection Report TÜV No. 722325629/01 of 03.07.2023



Roberto Bozza

CERTIFICATION DATE

03.07.2023



Fabio Locatelli

GHIBSON
valves
Ghibson Italia srl
Via Dozza, 2
40069 Zola Predosa BO Italy
C.F. 03170000372 P.IVA 00800571200

Handwritten signature